



CUSTOMER INVOICE

\*\*\*\*\*  
 \* GREATWEST KENWORTH LTD \*  
 \* 5909 - 6 STREET S.E. \*  
 \* CALGARY, ALBERTA T2H 1L8 \*  
 \* (403)253-7555 \*  
 \*\*\*\*\*

L253

\*  
09-11-07

CUSTOMER NAME  
 JBM LOGISTICS  
 615315 SASKATCHEWAN LTD  
 875 58 ST E  
 SASKATOON, SK S7K 6X5

NUMBER 5505  
 PHONE 306 653-5400  
 P.O. NO. 215386  
 COMPLETE 09-11-07

REPAIR ORDER NUMBER  
 >>>> NC18976 <<<<  
 DATE 09-10-07 16:04  
 SVC WTR DA \*MA

SERIAL NO. 1XKWD49X95J985085  
 YEAR/MAKE/MODEL - 2005 KENWORTH W900  
 ENGINE/MODEL/SERL  
 TRNS/MODEL/SERL -  
 RXLS MODEL/SERL -  
 SELL DLR

UNIT NO. L253

MILEAGE 493196  
 LICENSE  
 CPL/ARRG  
 R RATIO

DEL DATE

DEL MILE

POSTED

1 UNIT NEEDS POWER DIVIDER LOCKED IN TO MOVE  
 GIVE CUSTOMER THE OPTION OF R+R WITH REMAN DIFF OR REBUILD  
 CALL WITH QUOTE

CAUSE:

SPIN OUT.

CORRECTION:

REMOVE BOTH REAR DRIVE AXLE SHAFTS.LEFT AXLE BROKEN,PUSH OUT BROKEN  
 PIECE FROM RIGHT SIDE.DRAIN OIL AND INSPECT OK.NO METAL IN ETHER  
 WHEEL.AXLE BROKE IN ONLY TWO PIECES.INSTALLED NEW LEFT AXLE AND  
 OLD RIGHT AXLE.FILL WITH NEW FLUID.CLEAN WHEELS AND DISPOSE OF OLD  
 OIL.

TOTAL LABOR 375.00  
 TOTAL PARTS 431.56

1	127437	SHAFT-AXL	186.99
1	107276SETN	GASKET-RT	10.40
1	0287	BRAKEWASH	5.90
1	KEN75W90PL	SYNTHETIC	223.27
1	KEN75W90PL&	ENV CHG	5.00

CONTINUED

WO#13283

\*\*\*\*\*  
 \* GREATWEST KENWORTH LTD \*  
 \* 5909 - 6 STREET S.E. \*  
 \* CALGARY, ALBERTA T2H 1L8 \*  
 \* (403) 253-7555 \*  
 \*\*\*\*\*

CUSTOMER INVOICE  
 PAGE 2

\*  
 09-11-07

CUSTOMER NAME  
 JBM LOGISTICS

NUMBER 5505  
 PHONE 306 653-5400

REPAIR ORDER NUMBER  
 >>>> NC18976 <<<<

2 WHILE ON THE CALL WITH THE QUOTE ASK DON IF WE SHOULD DO THE A/C  
 AS PER DRIVER

CAUSE:  
 FAULTY HEATER SHUT OFF VALVE, FAN CONTROL SWITCH AND PLUGGED AC  
 CONDENSOR.

CORRECTION:  
 REPLACED HEATER SHUT OFF VALVE. REPLACED FAN CONTROL SWITCH, EVACUATED  
 AC SYSTEM AND CHECKED LEVEL OF REFREGERANT, DOWN 1 POUND, CHECKED FOR  
 LEAKS, NONE FOUND. ADDED DYE TO SYSTEM AND RECHARGED SYSTEM. WASHED OUT  
 PLUGGED AC CONDENSOR AND RAD. AC RUN AT 40 DEGRESS AND FAN CYCLES  
 30 SEC. OK.

TOTAL LABOR 437.50  
 TOTAL PARTS 80.62

1	MA1680	VALVE-WAT	36.57
2	ET-10	CLAMP	1.90
1	79PSL3-4	SWITCH-FA	20.07
1	622290	NUT- PUSH	0.48
2	16-834	50/50HD	21.18
1	CAP-M9	CAP-M9	0.42

SHOP SUPPLIES 24.38

-----  
 G.S.T. - REG. NO. R139766661 6 % OF 1349.06 = 80.94

CUST MECH LAB-CAL 812.50  
 PARTS CUSTOMER R/O-CAL 512.18  
 SHOP SUPPLIES-SHOP A 24.38  
 G.S.T. R139766661 80.94  
 PLEASE PAY THIS TOTAL 1430.00

CONTINUED

1349.06

\*\*\*\*\*  
 \* GREATWEST KENWORTH LTD \*  
 \* 5909 - 6 STREET S.E. \*  
 \* CALGARY, ALBERTA T2H 1L8 \*  
 \* (403)253-7555 \*  
 \*\*\*\*\*

CUSTOMER INVOICE  
 PAGE 3

\*  
 09-11-07

CUSTOMER NAME  
 JBM LOGISTICS

NUMBER 5505  
 PHONE 306 653-5400

REPAIR ORDER NUMBER  
 >>>> NC18976 <<<<

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items

Great West Kenworth Ltd. makes the limited warranty covering any defect in workmanship or material furnished in connection with this repair order for a period of thirty (30) days from the date of delivery of said motor vehicle to the customer/owner, or 16,000 kilometers whichever occurs first.

It is understood that a lien may be placed thereon for the amount due in case the vehicle repairs are not paid in full

Signature \_\_\_\_\_ Date \_\_\_\_\_

